

**CHEVRON USA INC - 16700**  
**API# 05-103-07475 LEVISON #32X**  
**Inspection Date : 7/14/2021**



Injection wellhead during MIT

**Click here to reset the form**

**State of Colorado**  
**Oil and Gas Conservation Commission**

**MECHANICAL INTEGRITY TEST**

**Well Information:**  
 Well Name: **LEVISON 32X**  
 Well ID: **05-103-07475**  
 Well Status: **Producing**  
 Well Type: **Oil**  
 Well Depth: **12,250**  
 Well Completion: **12,250**  
 Well Completion Date: **07/14/2021**

**Operator Information:**  
 Operator Name: **Chevron USA Inc**  
 Operator Address: **100 Centennial Road**  
 Operator City: **Rangely**  
 Operator State: **CO**  
 Operator Zip: **81648**  
 Operator Phone: **970-834-6441**  
 Operator Email: **levi32x@chevron.com**

**Test Information:**  
 Test Type: **SWIFT-IN PRODUCTION WELL**  
 Test Date: **07/14/2021**  
 Test Time: **12:06**  
 Test Location: **12,250**  
 Test Results: **12,250**  
 Test Status: **Pass**

**Signatures:**  
 Inspector: **Archie Blandford**  
 Inspector Title: **Inspection Specialist**  
 Inspector Date: **07/14/2021**  
 Inspector Signature: **Archie Blandford**  
 Operator Signature: **Archie Blandford**  
 Operator Title: **Inspection Specialist**  
 Operator Date: **07/14/2021**  
 Operator Signature: **Archie Blandford**

Form 21 field copy