

Inspection Photos
Location Name: W. Animas University #9-2
API: 05-067-07864



West Animas University #9-2 location photo.



Stained gravel beneath prime mover exhaust.

Inspection Photos
Location Name: W. Animas University #9-2
API: 05-067-07864



Concrete pad is wet and stained.



PBV labels have previous operator contact information posted. Comply with Rule 605.h.