

Inspection Photos

Location Name: THRALL USX AA-66N63W /19SESW

Location #: 310825



Photo #1

Thrall USX AA 19-14 (05-123-27050) Wellsite

Plugged & Abandoned | PA

~ 120 yds.



Photo #2

Thrall USX AA 19-14, 19-11, 19-12, 19-13, 19-25

Battery site

Abandoned: ALL Equipment Removed