


## Inspection Photos

Location Name: THRALL - USX AA-66N63W /19SWSW

Location #: 306327



**Photo #1**

**Thrall - USX AA 19-13 (05-123-24445) Wellsite**

**Plugged & Abandoned | PA**

**~ 240 yds.**



**Photo #2**

**Thrall USX AA 19-14, 19-11, 19-12, 19-13, 19-25**

**Battery site**

**Abandoned: ALL Equipment Removed**