

Inspection Photos

Location Name: THRALL-USX AA-66N63W /19NWSW

Location #: 310512




Photo #1

Thrall - USX AA 19-25 (05-123-26516) Wellsite

Plugged & Abandoned | PA

~ 320 yds.



Photo #2

Thrall USX AA 19-14, 19-11, 19-12, 19-13, 19-25

Battery site

Abandoned: ALL Equipment Removed