

Inspection Photos

Location Name: THRALL -USX AA-66N63W /19NWSW

Location #: 310827



Photo #1

Thrall - USX AA 19-12 (05-123-27052) Wellsite

Plugged & Abandoned | PA

~ 55 yds.



Photo #2

Thrall USX AA 19-14, 19-11, 19-12, 19-13, 19-25

Battery site

Abandoned: ALL Equipment Removed