

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/16/2021

Submitted Date:

07/17/2021

Document Number:

696104722

FIELD INSPECTION FORM

Loc ID 310825 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287205	WELL	PA	12/19/2018	OW	123-27050	THRALL USX AA 19-14	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / ABANDONED BATTERY** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Abandoned. ALL equipment removed.
Abandoned Battery SE corner GPS coordinates: 40.465111 / -104.482124

Abandoned Centralized Battery formerly served 5 Location IDs (310825, 306327, 310512, 310826, 310827).
(Well(s): 5: Plugged & Abandoned | PA).

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type		#			corrective date
Gas Meter Run		# 0			
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				
Corrective Action:					Date:
Pig Station		# 0			
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				
Corrective Action:					Date:
Horizontal Heated Separator		# 0			
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				
Corrective Action:					Date:
Emission Control Device		# 0			
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	0				,		
Comment:		Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				Date:	
Corrective Action:						Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No		
Comment:		
Corrective Action:	Date:	

Flaring:

Type		
Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 287205 Type: WELL API Number: 123-27050 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 07/16/2021 at approximately 14:31 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: THRALL USX AA-66N63W /19SESW Location ID: 310825 Well Name(s): Thrall USX AA 19-14. API: 05-123-27050. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment removed. Abandoned Battery SE corner GPS coordinates: 40.465111 / -104.482124</p> <p>Abandoned Centralized Battery formerly served 5 Location IDs (310825, 306327, 310512, 310826, 310827). (Well(s): 5: Plugged & Abandoned PA).</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Well appears to be cut / capped. Form 6 doc. #401656018 indicates plugging, cut/cap date: 12/19/2018. Approved.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	07/17/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104723	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5481287