

# Construction and Stormwater Inspection

July 16, 2021

Operator: VERDAD RESOURCES LLC #10651

Location ID: 474767

Inspection Document #:697503067

Weld County, CO

SWSE Section 31 T1N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name:County Line /Pad  
Location ID: 474767



**Photo 1.** Photo taken from the entrance of location, facing West. Photo illustrates current conditions along the county road. At the time of this inspection, no vehicle track out was observed. Operator has not yet installed a vehicle tracking device BMP.



**Photo 2.** Photo taken from the entrance of location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name:County Line /Pad  
Location ID: 474767



**Photo 3.** Photo taken from the southern location, facing East. Photo illustrates Operator has commenced construction activities and is in process of construction.



**Photo 4.** Photo taken from the southern location, facing North. See comments under Photo 3.

Inspection Photos  
Location Name:County Line /Pad  
Location ID: 474767



**Photo 5.** Photo taken from the northeastern location, facing North. Photo illustrates Operator has failed to install perimeter stormwater BMPs during construction activities.



**Photo 6.** Photo taken from the northeastern location (just east of the topsoil stockpile), facing West. See comments under Photo 5.

Inspection Photos  
Location Name:County Line /Pad  
Location ID: 474767



**Photo 7.** Photo taken from the northern location, facing West. Photo illustrates the topsoil stockpile which has been temporarily stabilized with equipment tracking.

Inspection Photos  
Location Name:County Line /Pad  
Location ID: 474767



**Photo 8.** Photo taken from the northwestern location, facing West. Photo illustrates Operator has failed to install perimeter stormwater BMPs during construction activities.



**Photo 9.** Photo taken from the northwestern location, facing South. See comments under Photo 8.

Inspection Photos  
Location Name:County Line /Pad  
Location ID: 474767



**Photo 10.** Photo taken from the southwestern location, facing South. See comments under Photo 8.



**Photo 11.** Photo taken from the southwestern location, facing East. See comments under Photo 8.