

Inspection Photos
Operator: Kinder Morgan
API: 083-06240
Date: 7/16/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with rubber rabbitbrush, western wheatgrass, and crested wheatgrass.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View the reference area comprised of sagebrush shrubland and pinyon/juniper woodland with understory of James galleta, purple threeawn, Indian ricegrass, and Palmer's penstemon.