

**Inspection Photos**  
**Operator: Kinder Morgan**  
**API: 083-06458**  
**Date: 7/16/2021**



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the northeastern project area from the northeastern corner facing westward. Revegetation is progressing with crested wheatgrass, James galleta, western wheatgrass, sagebrush, and rubber rabbitbrush.



Photo 3. View of the northwestern project area from the northwestern corner facing eastward.



Photo 4. View the reference area comprised of pinyon and juniper woodland with understory of shrubs such as sagebrush, serviceberry, antelope bitterbrush, and grasses/forbs such as James galleta and Palmer's penstemon.