

Inspection Photos
Operator: Kinder Morgan
API: 083-06387
Date: 7/16/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with crested wheatgrass, James galleta, snakeweed, sagebrush, and rubber rabbitbrush.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View the reference area comprised of pinyon and juniper woodland with understory of shrubs such as sagebrush, serviceberry, antelope bitterbrush, and grasses/forbs such as James galleta and Palmer's penstemon.