

Inspection Photos

Operator: Kinder Morgan
API: 083-06380
Date: 7/16/2021



Photo 1. View the project area from the northern well pad entrance facing center.



Photo 2. View of the northeastern project area from the northern corner facing southeastward. Revegetation is progressing with crested wheatgrass, James galleta, fourwing saltbush, sagebrush, and rubber rabbitbrush.



Photo 3. View of the southwestern fill slope from the northwestern corner facing southeastward.



Photo 4. View the reference area comprised of pinyon and juniper woodland with understory of shrubs such as sagebrush, serviceberry, antelope bitterbrush, and grasses/forbs such as James galleta and Palmer's penstemon.