

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2021

Submitted Date:

07/19/2021

Document Number:

700703011**FIELD INSPECTION FORM**

Loc ID 335082	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 13 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
------------------	----------------------------------	---	-------------------	--

Operator Information: OGCC Operator Number: <u>10531</u> Name of Operator: <u>GRIZZLY OPERATING LLC</u> Address: <u>5847 SAN FELIPE #3000</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77057</u>	ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE
--	---

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282960	WELL	PR	03/21/2008	GW	045-11888	MCLAUGHLIN 32C-27-692	PR
282962	WELL	PR	03/29/2008	GW	045-11887	MCLAUGHLIN 32B-27-692	PR
282963	WELL	PR	03/30/2008	GW	045-11886	MCLAUGHLIN 42B-27-692	PR
282964	WELL	PR	03/23/2008	GW	045-11885	MCLAUGHLIN 42C-27-692	PR
292117	WELL	PR	03/25/2008	GW	045-14597	MCLAUGHLIN 32D-27-692	PR
292118	WELL	PR	03/21/2008	GW	045-14596	MCLAUGHLIN 32A-27-692	PR
292120	WELL	PR	03/16/2008	GW	045-14595	MCLAUGHLIN 42A-27-692	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 7/19/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Mclaughlin, at Location # 335082 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.

C/A's from previous inspection document # 700702271 have been satisfied.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:				corrective date
Type: Gas Meter Run	# 7			
Comment:				
Corrective Action:				Date:
Type: Other	# 1			
Comment:	gas lift injection rack			
Corrective Action:				Date:
Type: Bird Protectors	# 9			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 7			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 8			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heater Treater	# 1			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	chemical tank at injection rack in plastic containment			
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 7			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	5	OTHER	HEATED STEEL AST		,	
Comment:	375 bbl tanks and One (1) tank is NOT heated					
Corrective Action:					Date:	

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Ramsey, Scott

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	282960	Type:	WELL	API Number:	045-11888	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	282962	Type:	WELL	API Number:	045-11887	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	282963	Type:	WELL	API Number:	045-11886	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	282964	Type:	WELL	API Number:	045-11885	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	292117	Type:	WELL	API Number:	045-14597	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	292118	Type:	WELL	API Number:	045-14596	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	292120	Type:	WELL	API Number:	045-14595	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts						
		Ditches				
Berms						
Ditches						
		Culverts				
		Check Dams				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703016	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5482947