

Inspection Photos
Location Name: Kerbs 1
Location ID: 317900



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Kerbs 1
Location ID: 317900



Photo 3 TB sign



Photo 4 TB

Inspection Photos

Location Name: Kerbs 1
Location ID: 317900



Photo 5 Gas Meter Run




Photo 6 Card indicates current calibration

Inspection Photos
Location Name: Kerbs 1
Location ID: 317900




Photo 7 Horizontal Heated Separator



Photo 8 Pig station