

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/19/2021

Submitted Date:

07/19/2021

Document Number:

699304104

**FIELD INSPECTION FORM**
 Loc ID 456589 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456573	WELL	PR	08/19/2019	OW	123-47567	BAJA BERG 35-5HZ	PR
456578	WELL	PR	08/12/2019	OW	123-47569	BAJA BERG 35-9HZ	PR
456583	WELL	PR	08/17/2019	OW	123-47573	BAJA BERG 35-4HZ	PR
456585	WELL	PR	08/13/2019	OW	123-47574	BAJA BERG 35-6HZ	PR
456588	WELL	DG	09/15/2018	OW	123-47577	BAJA BERG 35-7HZ	ND
456592	WELL	PR	08/16/2019	OW	123-47580	BAJA BERG 35-1HZ	PR
456594	WELL	PR	08/17/2019	OW	123-47582	BAJA BERG 35-3HZ	PR
456597	WELL	PR	08/12/2019	OW	123-47585	BAJA BERG 35-8HZ	PR
456599	WELL	PR	08/15/2019	OW	123-47586	BAJA BERG 35-2HZ	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Ag fence		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Chain link topped with barb wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: LACT	# 2		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 9		

Comment:			
Corrective Action:		Date:	
Type: FWKO	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 20		
Comment:	Electric panels, transformers, automation and corrosion inhibitor		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration record has been submitted in FIRR Doc # 402733518		
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	286 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	shares containment with PW tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	OTHER	STEEL AST		,
Comment:					
Corrective Action:					

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	286 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Wells Served By Facilities Above**

API Number
123-47586
123-47580
123-47582
123-47574
123-47573
123-47585
123-47567
123-47569

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 456573 Type: WELL API Number: 123-47567 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 12/17/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Facility ID: 456578 Type: WELL API Number: 123-47569 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 02/25/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 456583 Type: WELL API Number: 123-47573 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 12/17/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Facility ID: 456585 Type: WELL API Number: 123-47574 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 12/18/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Facility ID: 456588 Type: WELL API Number: 123-47577 Status: DG Insp. Status: ND

Facility ID: 456592 Type: WELL API Number: 123-47580 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 12/17/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Facility ID: 456594 Type: WELL API Number: 123-47582 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 11/16/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 456597 Type: WELL API Number: 123-47585 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 06/22/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 60 Fluid Type: LIQUID HYDROCARBON

End Surf Csg Pressure: 1

Comment:

Corrective Action:  Date:

Facility ID: 456599 Type: WELL API Number: 123-47586 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 11/16/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 7/19/2021 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p>Baja Berg 11-35HZ Pad at Location #456589 in Weld County Colorado.</p> <p>While there, I observed a Multi well pad and tank battery, PR at the time of inspection. During this inspection the following compliance issue has been addressed:</p> <p>430 Gas Meter Calibration: Card was submitted via FIRR Doc # 402733518.</p> <p>See attached photos.</p> <p>Location: dry, Weather: clear.</p> <p>No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	07/19/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304105	Calibration card	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5483054">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5483054</a>
699304106	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5483055">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5483055</a>