

Inspection Photos

API: 125-12057

Operator: PETRON DEVELOPMENT COMPANY

Inspection Date: 7/13/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 125-12057 | Date: 7/13/2021

Inspection Photos



Photo 1. Facing northwest along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-12057 | Date: 7/13/2021

Inspection Photos



Photo 2. Facing northwest toward the location. The well site area has not re-established vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-12057 | Date: 7/13/2021

Inspection Photos



Photo 3. Facing east at the location. This area lacking vegetation cover was measured to be approximately 50'x30' area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-12057 | Date: 7/13/2021

Inspection Photos



Photo 4. Facing southeast at the location which shows the area of the well site has not re-established vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-12057 | Date: 7/13/2021

Inspection Photos



Photo 6. Facing north at the surrounding undisturbed area which consists of Prairie Sandreed, Sand sage, Sand dropseed, among other native vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-12057 | Date: 7/13/2021