

Inspection Photos
Location Name: Anschutz State 5-61-19-20 SWSW PAD
Location ID: 437199



Photo 1 – Wellheads



Photo 2 – Well Stakes to the South

Inspection Photos
Location Name: Anschutz State 5-61-19-20 SWSW PAD
Location ID: 437199



Photo 3 – Tank Battery Signage



Photo 4 – Tank Battery



Inspection Photos
Location Name: Anschutz State 5-61-19-20 SWSW PAD
Location ID: 437199



Photo 5 – ECDs and Separators



Photo 6 – VRUs



Inspection Photos
Location Name: Anschutz State 5-61-19-20 SWSW PAD
Location ID: 437199




Photo 7 – 1" Riser at ECDs Unmarks



Photo 8 – 4" Unmarks Riser

