

Inspection Photos
Location Name: Anschutz Williams 5-61-27 SWSW
Location ID: 452726



Colorado Oil and Gas Conservation Commission
40.36557, -104.20382, 4569.6ft, 102°
07/19/2021 14:40:43



Colorado Oil and Gas Conservation Commission
40.3666, -104.20352, 4573.3ft, 276°
07/19/2021 14:43:23

Photo 1 – Tank Battery Sign

Photo 2 – Wellheads



Inspection Photos
Location Name: Anschutz Williams 5-61-27 SWSW
Location ID: 452726



Photo 3 – Riser STILL NOT MARKED

Photo 4 – Risers have been marked

Inspection Photos
Location Name: Anschutz Williams 5-61-27 SWSW
Location ID: 452726



Photo 5 – Separators