

LASSO OIL & GAS LLC
LITTLE GILLIAM-61N101W 3NWSW
Location # 311813



Sign at intersection.



Pump jack on Little Gilliam 1
Api # 05-103-07380

LASSO OIL & GAS LLC
LITTLE GILLIAM-61N101W 3NWSW
Location # 311813



LASSO OIL & GAS LLC
LITTLE GILLIAM-61N101W 3NWSW
Location # 311813



No operator contact number on tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

LASSO OIL & GAS LLC
LITTLE GILLIAM-61N101W 3NWSW
Location # 311813



Sediment stacking against tank.



Oil seeping through bolts on man cover.

LASSO OIL & GAS LLC
LITTLE GILLIAM-61N101W 3NWSW
Location # 311813



**Tank built along unstable cut slope. Rocks falling
and sediment moving into tank.**

LASSO OIL & GAS LLC
LITTLE GILLIAM-61N101W 3NWSW
Location # 311813



2" pipes on backside on tank berm.



Unused open ended 2" tubing inside on tank berm.

LASSO OIL & GAS LLC
LITTLE GILLIAM-61N101W 3NWSW
Location # 311813



Berm and ditch not maintained.



Berm and ditch not maintained.

LASSO OIL & GAS LLC
LITTLE GILLIAM-61N101W 3NWSW
Location # 311813



**Washing and sediment movement on roadways up
to tank battery.**

LASSO OIL & GAS LLC
LITTLE GILLIAM-61N101W 3NWSW
Location # 311813



Hole or burro in cellar around wellhead.

LASSO OIL & GAS LLC
LITTLE GILLIAM-61N101W 3NWSW
Location # 311813



Sediment movement on roadside of access road.



Storm water has washed out berm along access road. (40.08660 108.72430)