

Inspection Photos
Location Name: Perino Water Transfer Station
Location ID: 419311



Access road entrance off of CR 977. Previous operator listed on location signs.



Perino Water Transfer Station location photo.

Inspection Photos
Location Name: Perino Water Transfer Station
Location ID: 419311



Weeds present within secondary containment area. Tank label on western AST is illegible.



Weeds present near fired equipment.

Inspection Photos
Location Name: Perino Water Transfer Station
Location ID: 419311



Secondary containment berm has been breached.



Down gradient view of secondary containment berm.

Inspection Photos
Location Name: Perino Water Transfer Station
Location ID: 419311



Flow path of produced water from Spill/Release Point ID #480299.



Area impacted by Spill/Release Point ID #480299.