

Inspection Photos
Location Name: Dwinell 3
Location ID: 324592



Photo 1. Overview of location taken facing northeast.



Photo 2. Stained soil.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources