

Inspection Photos
Location Name: Jones 1-11
Location ID: 316760



Photo 1. Overview of location taken facing west. Workover equipment stored on location.



Photo 2. Tank without label.



Inspection Photos
Location Name: Jones 1-11
Location ID: 316760



Photo 3. Stained soil.



Photo 4. Stained soil at wellhead. No bradenhead access apparent.

Inspection Photos
Location Name: Jones 1-11
Location ID: 316760



Photo 5. Stained soil.



Photo 6. Annual weeds growing on/in tank battery berm.

