

Inspection Photos
Operator: Benson Montin Greer
API: 067-06159
Date: 7/20/2021



Photo 1. View of the project area from the northeastern corner facing center. Area is recontoured and graded. Germination not observed.



Photo 2. View of the project area from the southern edge facing center.



Photo 3. View the reference area comprised of pinyon and juniper woodland with scattered ponderosa pine trees and rubber rabbitbrush, smooth brome, and sagebrush in the understory.