

Inspection Photos
Location Name: Apache 33-B20
API # : 043-06157



Well sign



Inspection Photos
Location Name: Apache 33B-20
API #: 043-06157



No breardenhead access



Leak/impacted material inside containment



Inspection Photos
Location Name: Apache 33B-20
API #: 043-06157



Dead vegetation debris/combustible material in containment berms, no battery sign, only DOT placard for contents labelling



Tanks and placards

