

Inspection Photos
Location Name: Woolly Bugger 34-20
Api # : 043-06194



Well sign, difficult to read due to placement of chemical barrel

Inspection Photos
Location Name: Wooley Bugger 34-20
API #: 043-06194



No breaddenhead access, stained soils/impacted material around wellhead



Faded/deteriorated labeling on chemical container