

**Inspection Photos**  
**Location Name: RSU-Anschutz 4-62-11-12 SE10**  
**Location ID: 454976**



**Photo 1 – Wellheads**



**Photo 2 – Tank Battery**

Inspection Photos  
Location Name: RSU-Anschutz 4-62-11-12 SE10  
Location ID: 454976



Photo 3 – Tank Battery Sign



Photo 4 – Label Installed – Starting to Peel



**Inspection Photos**  
**Location Name: RSU-Anschutz 4-62-11-12 SE10**  
**Location ID: 454976**



**Photo 5 – Label Installed – Starting to Peel**



**Photo 6 – Label Installed – Starting to Peel**



## Inspection Photos

Location Name: RSU-Anschutz 4-62-11-12 SE10

Location ID: 454976



**Photo 7 – Label Installed**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources