

Inspection Photos

API: 071-09017

Operator: WAPITI OPERATING LLC

Inspection Date: 7/22/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09017 | Date: 7/22/2021

Inspection Photos



Photo 1. Facing southwest toward the access road. There are noxious weeds that are wilted along the access road. (shown at red arrow)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09017 | Date: 7/22/2021

Inspection Photos



Photo 2. There were some noxious weeds that weren't treated. The red arrow points to biennial Houndstongue which has produced seed. The yellow arrow points to Houndstongue first year growth which will produce seed next year.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09017 | Date: 7/22/2021

Inspection Photos



Photo 3. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09017 | Date: 7/22/2021