

Attachment B



WELLHEAD ABANDONMENT FORM

SITE NAME: Fox 42-24 Wellhead							DATE: 4/20/2021	REM. PROJECT #: 17015	WEATHER: 30's Sunny		
SITE DIRECTIONS: CR 13/20, 0.2 mi E, SE into							CLIENT: PDC				
LEGALS AND LAT/LONG: 40.125418, -104.942954							TASMAN PERSONNEL: Jesse Marcus				
SOIL TYPES: Clayey Sand - SC							SURFACE GRADIENT: South				
SOIL SAMPLING							FACILITY INFRASTRUCTURE				
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity		
							Above Ground Storage Tank (AST)				
4/20/2021 12:50	FLR01@5'	0.0	No Staining	No Odor	Yes	Lab	Buried or Partially Buried Vessel				
4/20/2021 12:51	WH01@2.5'	0.0	No Staining	No Odor	Yes	Lab	Separator				
4/20/2021 13:16	WHS01-N@0-6"	0.2	No Staining	No Odor	Yes	Grab	Emission Control Device (ECD)				
4/20/2021 13:17	WHS01-W@0-6"	0.0	No Staining	No Odor	Yes	Grab	Dump Line				
4/20/2021 13:18	WHS01-S@0-6"	0.0	No Staining	No Odor	Yes	Grab	Wellhead		1		
4/20/2021 13:19	WHS01-E@0-6"	0.0	No Staining	No Odor	Yes	Grab	Flowline		1		
4/20/2021 14:19	BKG01@2.5'	0.0	No Staining	No Odor	Yes	On-Hold	Other:				
							Soil Loads Removed				
							IMPACTED SOIL IDENTIFIED? No				
							ESTIMATED VOLUME OF IMPACTS:				
							Date		Number	CY	
							Total Removed		0	0	
							Disposal Facility:				
							Groundwater Recovery				
							DATE GW ENCOUNTERED: 4/20/2021		DEPTH: 4'		
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL? Groundwater not in contact with soil impacts.				
							LNAPL OR SHEEN OBSERVED ON GW? None Observed on GW.				
GROUNDWATER SAMPLING							Date		BBLS		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?					
4/20/2021 12:48	GW01	4	Medium Turbidity	None	None	Yes					
							Total Removed		0		
							Disposal Facility:				





Photographic Log

							
Equipment ID: FLR		Equipment Type: Wellhead		Equipment ID: WH		Equipment Type: Wellhead	
Material:		Volume:		Material:		Volume:	
		Contents:		Material:		Volume:	
				Material:		Volume:	
Notes/Conditions: FLR01 @5' and GW01				Notes/Conditions: WH01 @2.5'			

Photographic Log

											
Equipment ID: WHS		Equipment Type: Wellhead		Equipment ID: WHS		Equipment Type: Wellhead					
Material:		Volume:		Contents:		Material:		Volume:		Contents:	
Notes/Conditions: WHS01-N@0-6"						Notes/Conditions: WHS01-W@0-6"					

Photographic Log

							
Equipment ID: WHS		Equipment Type: Wellhead		Equipment ID: WHS		Equipment Type: Wellhead	
Material:		Volume:		Material:		Volume:	
Contents:				Contents:			
Notes/Conditions: WHS01-S@0-6"				Notes/Conditions: WHS01-E@0-6"			

Photographic Log

							
Equipment ID: BKG		Equipment Type: Wellhead		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions: BKG01 @ 2.5'				Notes/Conditions: Wellhead cut & cap			