

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402758895

Date Received:
07/26/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

NBL_DJBU_Inspections@NBLENERGY.COM

COGCC INSPECTION SUMMARY:

FIR Document Number: 699104016

Inspection Date: 07/12/2021

FIR Submit Date: 07/12/2021

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 310657

Location Name: LOCKMAN C-64N64W Number: 10NESE County: _____

Qtrqr: NESE Sec: 10 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.323331 Longitude: -104.527899

FACILITY - API Number: 05-123- -00 Facility ID: 310657

Facility Name: LOCKMAN C-64N64W Number: 10NESE

Qtrqr: NESE Sec: 10 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.323331 Longitude: -104.527899

CORRECTIVE ACTIONS:

1 ☒ CA# 152674

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 07/21/2021

Response: CA COMPLETED

Date of Completion: 07/23/2021

Operator Comment: Valves, pipes, fittings secured.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 152675

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 07/21/2021

Response: CA COMPLETED

Date of Completion: 07/23/2021

Operator
Comment: Valves, pipes, fittings secured.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 152676

Corrective Action: "Properly dispose of oily waste in accordance with 905.e."

Date: 07/21/2021

Response: CA COMPLETED

Date of Completion: 07/23/2021

Operator
Comment: Waste removed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Abby Jayeola

Signed: _____

Title: WFS

Date: 7/26/2021 7:55:56 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402758895	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files