

# Inspection Photos

7/21/2021

Operator: SG INTERESTS I LTD - 77330

Location ID: 414132

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 414132



**Photo 1:** Photo taken from the west end of the Location, facing south. Photo shows control measures to protect and stabilize the slopes on the west end of the Location remain missing, or insufficient.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 414132



**Photo 2:** Photo taken from the west end of the Location, facing northwest. Photo shows control measures to protect and stabilize the slopes on the west end of the Location remain missing, or insufficient.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 414132



**Photo 3:** Photo taken from the topsoil stockpile on the northwest end of the Location. Photos show control measures to protect and stabilize the soils at the stockpile remain missing, or insufficient.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 414132



July 21, 2021  
39.09873778N 107.38110986W

**Photo 4:** Photo taken from the cuts lope on the north end of the Location, facing northeast. Photo shows slopes have been regraded, and a hydromulch applied to stabilize the soils. This portion of the CA has been addressed.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 414132



**Photo 5:** Photo taken from the cuts lopes on the north end of the Location, facing west. Photo shows slopes have been regraded, and a hydromulch applied to stabilize the soils. This portion of the CA has been addressed.

