

Inspection Photos

7/22/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334713

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334713



Photo 1: Photo taken from the south end of the Location, facing north. Photo provides overview of the Location. Green vegetation in photo observed to be undesirable plant species (*Kochia* sp., *Salsola* sp.) established on the Location; weeds require management in accordance with Rule 606.c.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334713



Photo 2: Photo taken from the east end of the Location, facing north. Photo shows noxious weeds and undesirable plant species (*Kochia* sp., *Salsola* sp.) established on the Location; weeds require management in accordance with Rule 606.c and Rule 1003.f.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334713



Photo 3: Photo shows noxious weeds established on the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334713



Photo 4: Photo taken from the southwest corner of the Location, facing east. Photo shows example of Undesirable Plant Species (Kochia sp., Salsola sp.) established on the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334713



Photo 5: Photo taken from the west end of the Location. Photo shows example of weed debris accumulation observed within the vegetation and on the slopes of the Location.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334713



Photo 6: Photo taken from the west end of the Location. Photo shows example of weed debris accumulation and trash observed within the vegetation and on the slopes of the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334713



July 22, 2021
39.46955475N 107.91486363W

Photo 7: Photos 7-9 shows various equipment, vehicles, trailers, and trash observed stored on the north end of the Location. Pursuant to Rule 606, storage of equipment, vehicles, trailers, etc... not necessary for use on the Location is prohibited.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334713



Photo 8: See comments under photo 7.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334713



Photo 9: See comments under photo 7.

