

Inspection Photos

7/22/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335822

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335822



Photo 1: Photo taken from the diversion ditch along the north end of the Location, facing northeast. Photo shows example of areas within the ditch that are not stabilize resulting in erosion degradation offsite and up the slope. BMPs to protect and stabilize the slopes remain missing or insufficient.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335822



Photo 2: Photo taken from the diversion ditch along the north end of the Location, facing northeast. Photo shows example of areas within the ditch that are not stabilize resulting in erosion degradation offsite and up the slope. BMPs to protect and stabilize the slopes remain missing or insufficient.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335822



Photo 3: Photo taken from the interim slopes on the north end of the Location. Photo shows erosion degradation on the slopes; unable to find evidence that additional reclamation has been performed on these areas. BMPs to protect/stabilize slopes remain missing or insufficient.