

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36NESW

Location ID: 335145



Photo #4557 from entrance to location.



Photo #4558 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36NESW

Location ID: 335145



Photo #4559 No battery sign located at the tank battery.



Photo #4562 Wellhead sign weathered and not legible.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36NESW

Location ID: 335145



Photo #4560 Location lacks stabilization.



Photo #4561 Location lacks stabilization.