

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE-66S96W /36SWNE

Location ID: 335177



Photo #4563 from entrance to location.



Photo #4564 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE-66S96W /36SWNE

Location ID: 335177



**Photo #4565 No battery sign located at the tank battery.**