

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/27/2021

Submitted Date:

07/27/2021

Document Number:

679604061

FIELD INSPECTION FORM

Loc ID 454899	Inspector Name: Santistevan, Brittani	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10669 Name of Operator: NICKEL ROAD OPERATING LLC Address: 1600 STOUT STREET SUITE 1850 City: DENVER State: CO Zip: 80202				Findings: 30 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
,		jennifer.lind@nickelroadoperating.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454901	WELL	XX	06/18/2020		123-46773	DRAKE 2X-HNB-11-07-67	ND
454902	WELL	XX	06/18/2020		123-46774	DRAKE 2X-HC-11-07-67	ND
454903	WELL	XX	06/18/2020		123-46775	DRAKE 3X-HC-11-07-67	ND
454904	WELL	XX	06/18/2020		123-46776	DRAKE 1X-HC-11-07-67	ND
454905	WELL	XX	06/18/2020		123-46777	DRAKE 2X-HNC-11-07-67	ND
454906	WELL	XX	06/18/2020		123-46778	DRAKE 3X-HNB-11-07-67	ND
454907	WELL	XX	06/18/2020		123-46779	DRAKE 1X-HNC-11-07-67	ND
454908	WELL	XX	06/18/2020		123-46780	DRAKE 1X-HNB-11-07-67	ND
454909	WELL	XX	06/18/2020		123-46781	DRAKE 3X-HNC-11-07-67	ND
454910	WELL	XX	06/18/2020		123-46782	DRAKE 4X-HNB-11-07-67	ND
454911	WELL	PR	11/15/2019	OW	123-46783	DRAKE 4X-HNC-11-07-67	PR
454912	WELL	XX	06/18/2020		123-46784	DRAKE 4X-HC-11-07-67	ND
454913	WELL	PR	11/15/2019	OW	123-46785	DRAKE 5X-HC-11-07-67	PR
454914	WELL	PR	11/12/2019	OW	123-46786	DRAKE 5X-HNB-11-07-67	PR
454915	WELL	XX	06/18/2020		123-46787	DRAKE 5X-HNC-11-07-67	ND
454916	WELL	XX	06/18/2020		123-46788	DRAKE 6X-HC-11-07-67	ND
454917	WELL	XX	06/18/2020		123-46789	DRAKE 6X-HNB-11-07-67	ND
454918	WELL	XX	06/18/2020		123-46790	DRAKE 6X-HNC-11-07-67	ND
454919	WELL	XX	06/18/2020		123-46791	DRAKE 7X-HNB-11-07-67	ND
454920	WELL	XX	06/18/2020		123-46792	DRAKE 7X-HC-11-07-67	ND
454921	WELL	XX	06/18/2020		123-46793	DRAKE 8X-HNB-11-07-67	ND

454922	WELL	XX	06/18/2020		123-46794	DRAKE 8X-HNC-11-07-67	ND
454923	WELL	XX	06/18/2020		123-46795	DRAKE 8X-HC-11-07-67	ND
454924	WELL	XX	06/18/2020		123-46796	DRAKE 7X-HNC-11-07-67	ND

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds on various spots of location. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	08/10/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	

Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	5	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	5	400 BBLS	FIBERGLASS AST		,	
Comment:						
Corrective Action:						

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with crude oil tanks.				
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 454901 Type: WELL API Number: 123-46773 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: NOT DRILLED

Form 2 DOC#: 402372297 expires JUNE 2022

Corrective Action: 2 Date:

Facility ID: 454902 Type: WELL API Number: 123-46774 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: NOT DRILLED

Form 2 DOC#: 402372279 expires JUNE 2022

Corrective Action: Date:

Facility ID: 454903 Type: WELL API Number: 123-46775 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: NOT DRILLED

Form 2 DOC#: 402372347 expires JUNE 2022

Corrective Action: Date:

Facility ID: 454904 Type: WELL API Number: 123-46776 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: NOT DRILLED

Form 2 DOC#: 402371660 expires JUNE 2022

Corrective Action: Date:

Facility ID: 454905 Type: WELL API Number: 123-46777 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: NOT DRILLED

Form 2 DOC#: 402372331 expires JUNE 2022

Corrective Action: Date:

Facility ID: 454906 Type: WELL API Number: 123-46778 Status: XX Insp. Status: ND

Idle Well			
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION	
Comment: NOT DRILLED			
Form 2 DOC#: 402372366 expires JUNE 2022			
Corrective Action:		Date:	
Facility ID: 454907	Type: WELL	API Number: 123-46779	Status: XX Insp. Status: ND

Idle Well			
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION	
Comment: NOT DRILLED			
Form 2 DOC#: 402372197 expires JUNE 2022			
Corrective Action:		Date:	
Facility ID: 454908	Type: WELL	API Number: 123-46780	Status: XX Insp. Status: ND

Idle Well			
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION	
Comment: NOT DRILLED			
Form 2 DOC#: 402371768 expires JUNE 2022			
Corrective Action:		Date:	
Facility ID: 454909	Type: WELL	API Number: 123-46781	Status: XX Insp. Status: ND

Idle Well			
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION	
Comment: NOT DRILLED			
Form 2 DOC#: 402372514 expires JUNE 2022			
Corrective Action:		Date:	
Facility ID: 454910	Type: WELL	API Number: 123-46782	Status: XX Insp. Status: ND

Idle Well			
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION	
Comment: NOT DRILLED			
Form 2 DOC#: 402372873 expires JUNE 2022			
Corrective Action:		Date:	
Facility ID: 454911	Type: WELL	API Number: 123-46783	Status: PR Insp. Status: PR

Producing Well			
Comment: PR			
Corrective Action:		Date:	
Facility ID: 454912	Type: WELL	API Number: 123-46784	Status: XX Insp. Status: ND

Idle Well			
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION	
Comment: NOT DRILLED Form 2 DOC#: 402372756 expires JUNE 2022			
Corrective Action:		Date:	
Facility ID: 454913	Type: WELL	API Number: 123-46785	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	
Facility ID: 454914	Type: WELL	API Number: 123-46786	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	
Facility ID: 454915	Type: WELL	API Number: 123-46787	Status: XX Insp. Status: ND
Idle Well			
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION	
Comment: NOT DRILLED Form 2 DOC#: 402372960 expires JUNE 2022			
Corrective Action:		Date:	
Facility ID: 454916	Type: WELL	API Number: 123-46788	Status: XX Insp. Status: ND
Idle Well			
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION	
Comment: NOT DRILLED Form 2 DOC#: 402373082 expires JUNE 2022			
Corrective Action:		Date:	
Facility ID: 454917	Type: WELL	API Number: 123-46789	Status: XX Insp. Status: ND
Idle Well			
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION	
Comment: NOT DRILLED Form 2 DOC#: 402373118 expires JUNE 2022			
Corrective Action:		Date:	
Facility ID: 454918	Type: WELL	API Number: 123-46790	Status: XX Insp. Status: ND

Idle Well				
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION	
Comment:	<div>NOT DRILLED</div> <div>Form 2 DOC#: 402373142 expires JUNE 2022</div>			
Corrective Action:			Date:	
Facility ID:	454919	Type:	WELL	API Number: 123-46791 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION	
Comment:	<div>NOT DRILLED</div> <div>Form 2 DOC#: 402373195 expires JUNE 2022</div>			
Corrective Action:			Date:	
Facility ID:	454920	Type:	WELL	API Number: 123-46792 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION	
Comment:	<div>NOT DRILLED</div> <div>Form 2 DOC#: 402373166 expires JUNE 2022</div>			
Corrective Action:			Date:	
Facility ID:	454921	Type:	WELL	API Number: 123-46793 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION	
Comment:	<div>NOT DRILLED</div> <div>Form 2 DOC#: 402373258 expires JUNE 2022</div>			
Corrective Action:			Date:	
Facility ID:	454922	Type:	WELL	API Number: 123-46794 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION	
Comment:	<div>NOT DRILLED</div> <div>Form 2 DOC#: 402373271 expires JUNE 2022</div>			
Corrective Action:			Date:	
Facility ID:	454923	Type:	WELL	API Number: 123-46795 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION	
Comment:	<div>NOT DRILLED</div> <div>Form 2 DOC#: 402373241 expires JUNE 2022</div>			
Corrective Action:			Date:	

Facility ID:	454924	Type:	WELL	API Number:	123-46796	Status:	XX	Insp. Status:	ND
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: NOT DRILLED

Form 2 DOC#: 402373207 expies JUNE 2022

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>**Weather Conditions: sunny, dry ground</p> <p>On Tuesday, July 27, 2021 at approximately 14:45, I, Inspector Brittani Santistevan, conducted an on-site inspection at DRAKE PAD (Nickel Road Operating LLC), at location #: 454899 in WELD Colorado.</p> <p>While there, I observed a producing facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. Weeds on various spots of location. Remove to comply with Rule 606. (Corrective Action Date: August 10, 2021) See attached photos #3-6.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	07/27/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679604062	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5491115