

Inspection Photos

API: 071-09521

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/27/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 7/27/2021

Inspection Photos



Photo 1. Facing west at the access road and toward the fill slope of the location. There are signs of erosion along this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 7/27/2021

Inspection Photos



Photo 2. Facing southwest at the location. The location has not been recontoured and a step cut slope remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 7/27/2021

Inspection Photos



Photo 3. There is a pit that remains along the base of the cut slope at the locatoion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 7/27/2021

Inspection Photos



Photo 4. Facing east toward the pit at the base of the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 7/27/2021

Inspection Photos



Photo 5. There are 3 steel casings that remain at center of the location. The casing shown at red arrow is not covered to prevent entry. The steel casings need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 7/27/2021

Inspection Photos



Photo 6. Facing southeast toward the location. The abandoned location needs to be recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 7/27/2021

Inspection Photos



Photo 7. Facing east along the fill slope of the location which will need to be recontoured back into the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 7/27/2021

Inspection Photos




Photo 8. Facing southwest at the surrounding undisturbed vegetation which consists of Western wheat, Needle and thread grass, Sand drop seed, among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 7/27/2021