

Inspection Photos
Location Name: Ditlev-Simonson B #1
Location ID: 318206



Photo 1 WH sign



Photo 2 stained soil around WH

Inspection Photos
Location Name: Ditlev-Simonson B #1
Location ID: 318206



Photo 3 Ancillary Equipment



Photo 4 Pump Jack

Inspection Photos
Location Name: Ditlev-Simonson B #1
Location ID: 318206



Photo 5 tall weeds along access road and ROW



Photo 6 tall weeds along location ROW

Inspection Photos
Location Name: Ditlev-Simonson B #1
Location ID: 318206



Photo 7 trash old piece of poly pipe by ancillary equipment



Photo 8 tall weeds along location ROW