

Inspection Photos
Location Name: Fish Creek Unit 2 (8-20)
Location ID: 316745



Photo 1. Overview of location taken facing northwest.



Photo 2. Stained soil at wellhead. No bradenhead access apparent.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources