

Inspection Photos
Location Name: McCallum Unit 70
Location ID: 324617



Photo 1. Overview of location taken facing southeast.



Photo 2. No bradenhead access apparent.

