

**Inspection Photos**  
**Location Name: McCallum Unit 104**  
**Location ID: 324663**



**Photo 1. Overview of location taken facing north.**



**Photo 2. No bradenhead access apparent. Stained soil at wellhead.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources