

Inspection Photos
Location Name: Elk Springs Unit 4
Location ID: 311770



Photo 1. Overview of location taken facing north.

Inspection Photos
Location Name: Elk Springs Unit 4
Location ID: 311770



Photo 2. Wellhead sign incomplete.



Photo 3. Well shut in at time of inspection.