

Inspection Photos
Location Name: Elk Springs Unit 3
Location ID: 311768



Photo 1. Overview of location taken facing east.



Photo 2. Wellhead sign incomplete.

