

**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 17SESW**  
**Location # 315226**



**Sign is illegible.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 17SESW**  
**Location # 315226**



Sign is hung upside down. Legal description is illegible.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 17SESW**  
**Location # 315226**



No battery sign at tank battery. Label doesn't meet Rule 605.h. (missing information).



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 17SESW**  
**Location # 315226**



**Ball valve ¼ open. 150 psi on gauge.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 17SESW**  
**Location # 315226**



**No braden head access.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 17SESW**  
**Location # 315226**



**Location covered with weeds.**





**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 17SESW**  
**Location # 315226**



**Location covered with weeds.**



**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 17SESW**  
**Location # 315226**



**Wheel chart is turning.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 17SESW**  
**Location # 315226**

