

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 16NENE
Location # 315181



Access road and bmps not maintained.

**LASSO OIL & GAS LLC
CONTINENTAL-63S100W 16NENE
Location # 315181**



**A stormwater channel running most of the length
of the access road.**

**LASSO OIL & GAS LLC
CONTINENTAL-63S100W 16NENE
Location # 315181**



Weeds on location and road.



Road and storm water ditch not being maintained.

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 16NENE
Location # 315181



Location is covered by weeds.

**LASSO OIL & GAS LLC
CONTINENTAL-63S100W 16NENE
Location # 315181**



Deadman markers are not brightly colored.

Deadman markers are not brightly colored.

**LASSO OIL & GAS LLC
CONTINENTAL-63S100W 16NENE
Location # 315181**



Deadman markers are not brightly colored.

**LASSO OIL & GAS LLC
CONTINENTAL-63S100W 16NENE
Location # 315181**



Well sign is leaned up against separator.



Weeds around well and separator.

**LASSO OIL & GAS LLC
CONTINENTAL-63S100W 16NENE
Location # 315181**



**Spill at separator originating at broken sight glass.
No active leak observed at time of inspection.**

**Spill at separator originating at broken sight glass.
No active leak observed at time of inspection.**

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 16NENE
Location # 315181



Channeling off of location.

**LASSO OIL & GAS LLC
CONTINENTAL-63S100W 16NENE
Location # 315181**



Roll of wire fence off of location.



Tarp off of location.

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 16NENE
Location # 315181



Iron rod material off of location.

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 16NENE
Location # 315181



Tank berm covered by weeds.

**LASSO OIL & GAS LLC
CONTINENTAL-63S100W 16NENE
Location # 315181**



Last meter calibration on 6-13-2019.