

Inspection Photos
Operator: Arkoma
API: 067-05501
Date: 7/27/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and smooth brome.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of the reference area comprised of black sagebrush, big sagebrush, western wheatgrass, squirreltail, and penstemon.