

Inspection Photos
Operator: Simcoe
API: 067-08818
Date: 7/27/2021



Photo 1. View of the project area from the northern corner facing center.



Photo 2. View of the northeastern project area from the northern corner facing southeastward. Revegetation is progressing with western wheatgrass, crested wheatgrass, rubber rabbitbrush, and fourwing saltbush.



Photo 3. View of the northwestern project area from the northern corner facing southwestward.



Photo 4. View of the reference area comprised of pinyon and juniper woodland, with black sagebrush, big sagebrush, western wheatgrass, squirreltail, and penstemon.