

Inspection Photos

API: 071-07409

Operator: OGRIS OPERATING LLC

Inspection Date: 7/29/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07409 | Date: 7/29/2021

Inspection Photos



Photo 1. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07409 | Date: 7/29/2021

Inspection Photos



Photo 2. The shed panel still remains in disrepair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07409 | Date: 7/29/2021