

# Inspection Photos

API: 071-06408

Operator: OGRIS OPERATING LLC

Inspection Date: 7/29/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06408 | Date: 7/29/2021

## Inspection Photos



**Photo 1.** Facing northeast toward the location. The vegetation is not progressing and additional reseedling will need to be performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06408 | Date: 7/29/2021



## Inspection Photos



**Photo 2.** The location is not stabilized with vegetation cover. Additional seeding will need to be performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06408 | Date: 7/29/2021



## Inspection Photos



**Photo 3.** Facing southwest at the location. There are signs of erosion and vegetation is not progressing.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06408 | Date: 7/29/2021