

Inspection Photos

API: 071-09239

Operator: OGRIS OPERATING LLC

Inspection Date: 7/29/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09239 | Date: 7/29/2021

Inspection Photos



Photo 1. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09239 | Date: 7/29/2021

Inspection Photos



Photo 2. The fence around the pit is not maintained. This issue has been previously observed and needs adequately fenced and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09239 | Date: 7/29/2021