


Inspection Photos

Location Name: Aspen 3-65 15-14 3H_D

Location ID: 449376

ul 29, 2021 at 1:46:02 PM
39.757271,-104.659942
Monaghan Rd
Aurora CO 80019
United States
COGCC



Pic 1 stained soil by wellhead

ul 29, 2021 at 1:46:26 PM
39.793739,-104.657395
Aurora CO 80137
United States
COGCC



Pic 2



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Aspen 3-65 15-14 3H_D

Location ID: 449376

Jul 29, 2021 at 1:46:45 PM
39.793739,-104.657395
Aurora CO 80137
United States
COGCC



Pic 3



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources